Oil Field Environmental Incident Summary

Responsible Party: EMERALD OIL, INC **Well Operator:** EMERALD OIL, INC

Well Name: FEDERAL 12-15
Field Name: BOXCAR BUTTE
Well File #: 14861

Date Incident:3/16/2015Time Incident:14:00Facility ID Number:County:MCKENZIETwp:148Rng:102Sec:15Qtr:

Location Description:

Submitted By: Scott Anderson Received By:

Contact Person: Scott Anderson

1600 BROADWAY, SUITE 1360

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 3 Barrels 3 Barrels 3 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/6/2015 Clean Up Concluded: 3/17/2015

Risk Evaluation: LEL, hazardous waste

Areal Extent:

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Pumper understand he cannot leave pumps running without prior approval from management who have ensured such operations would not result in an incident

Wastes Disposal Location: Indian Hills

Agencies Involved:

Updates

Date: 3/17/2015 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.